#### **BOUNDARY SURVEY**

## LEGAL DESCRIPTION:

LOT 32, ALAQUA LAKES PHASE 1, ACCORDING TO THE PLAT THEREOF, AS RECORDED IN PLAT BOOK 52, PAGES 70 THROUGH 80, OF THE PUBLIC RECORDS OF SEMINOLE COUNTY, FLORIDA.


### FLOOD INFORMATION:

BY PERFORMING A SEARCH WITH THE LOCAL GOVERNING MUNICIPALITY OR WWW.FEMA.GOV, THE PROPERTY APPEARS TO BE LOCATED IN ZONE X. THIS PROPERTY WAS FOUND IN SEMINOLE COUNTY, COMMUNITY NUMBER 120289, DATED 2007-09-28.

#### **CERTIFIED TO:**

BERNARD BAJACAN





NOTES

NOTES

NOTES

NOTES

NOTES

Notiney is Based upon the Legal Description Supplied by Client.

Abutting Properties Deeds have NOT been Researched for Gaps, Overlaps and/or Hiatus.

Subject to any Easements and/or Restrictions of Record.

Reading basis Nown hereon, is Assumed and Based upon the Line Denoted with a "BB".

Sleuifing Ties are NOT to be used to reconstruct Property Lines.

Pence Ownership is NOT determined.

Roof Overhangs, Underground Utilities and/or Footers have NOT been located UNLESS otherwise noted.

Septic Tanks and/or Drainfield locations are approximate and MUST be verified by anarograted Little rotation Company. Drawn By: G.S. File Number: IS-115229 PC Point of Curvature
Pg. Page
Pi Point of Intersection
PO.B. Point of Beginning
P.O.L. Point on Line
P.O.L. Point on Line
PRM Permanent Reference
Monument
PT Point of Tangency
R Radius
R&C Rebar & Cap
R&C. Recovered
Rfd. Notice
Rebar
Typ. 1 Vipical
U Villity Easement
WM Vater Meter
WM Vater Meter
A Delta (Central Angle)
O Chain Link Fence -Legend-- Calculated - Centerline - Concrete Block - Concrete Monument - Concrete Patrick K. Ireland Company of Sald Certified Parties. This Survey NOT VALID UNIESS signed and Embossed with Survey of Seal. - Concrete
- Description
- Description
- Description
- Dralnage Easement
- Easement
- Easement
- Foderal Emergency
- Management Agency
- Found
- Found
- Iron Pipe
- Length (Arc)
- Measured
- Nall & Disk
- Non-Radial >>eptc I ainst and/or Dramheid locations are approximate and MUS1 be verified by appropriate Utility Location Compaints in Intended Without Written Verification, Will be at the User's Sole Risk and Without Lability to the Surveyor. Nothing Hereon shall be construed to give ANY Rights or Benefits to Anyone Other than those Certified. -POINTS OF INTEREST-DRIVEWAY, A/C PADS, AND SCREENED POOL DECK CROSSES EASEMENTS. Ireland & Associates Surveying, Inc. 800 Currency Circle | Suite 1020 Non-Radial
 Official Records Book
 Plat
 Plat Book Lake Mary, Florida 32746 www.irelandsurveying.com Office-407.678.3366 Fax-407.320.8165

## Description of Sketch

## Legal Description: Portion to Vacate

A PORTION OF THE EXISTING 15 FOOT UTILITY & DRAINAGE EASEMENT LOCATED ON LOT 32, ALAQUA LAKES PHASE 1, ACCORDING TO THE PLAT THEREOF, AS RECORDED IN PLAT BOOK 52, PAGES 70 THROUGH 80, OF THE PUBLIC RECORDS OF SEMINOLE COUNTY, FLORIDA, MORE PARTICULARLY DESCRIBED AS FOLLOWS:

COMMENCING AT THE NORTHWEST CORNER OF SAID LOT 32, THENCE WITH THE WESTERLY LINE OF SAID LOT 32, SOUTH 20°54'44" EAST, 15.10 FEET, TO A POINT ON THE SOUTHERLY LINE OF SAID EXISTING 15 FOOT UTILITY & DRAINAGE EASEMENT; THENCE DEPARTING THE WESTERLY LINE OF SAID LOT 32, AND WITH THE SOUTHERLY LINE OF SAID EXISTING 15 FOOT UTILITY & DRAINAGE EASEMENT, NORTH 62°25'50" EAST, 18.39 FEET, TO THE POINT OF BEGINNING.

THENCE DEPARTING THE SOUTHERLY LINE OF SAID EXISTING 15 FOOT UTILITY & DRAINAGE EASEMENT, RUN THE FOLLOWING (3) COURSES AROUND THE EXISTING SCREEN ENCLOSED POOL DECK: NORTH 14°20'52" WEST, 5.11 FEET; NORTH 60°14'54" EAST, 9.09 FEET; NORTH 75°51'43" EAST, 22.92 FEET, TO A POINT ON THE SOUTHERLY LINE OF SAID EXISTING 15 FOOT UTILITY & DRAINAGE EASEMENT; THENCE WITH THE SOUTHERLY LINE OF SAID EXISTING 15 FOOT UTILITY & DRAINAGE EASEMENT, SOUTH 62°25'50" WEST, 32.54 FEET, TO THE POINT OF BEGINNING.

CONTAINING 109.00 SQUARE FEET OR 0.002 ACRES, MORE OR LESS.

This is NOT a Survey. This is ONLY a Description.

This Sketch and Description consist of two sheets and is not full and or complete without both sheets.

Sketch Date: 02/28/23 Drawn By: BMJ Approved By: PKI

Sketch and Description Certified To:

## **BERNARD BAJACAN**

# Ireland & Associates Surveying, Inc.

800 Currency Circle Suite 1020 Lake Mary, Florida 32746

www.irelandsurveying.com

Office-407.678.3366 Fax-407.320.8165

-Notes->Sketch is Based upon the Legal Description Supplied by Client.

>Abutting Properties Deeds have <u>NOT</u> been Researched for Gaps, Overlaps and/or Hiatus.

>Subject to any Easements and/or Restrictions of Record

- >Bearing Basis shown hereon, is Assumed and Based upon the Line Denoted with a "BB'
- >Building Ties are NOT to be used to reconstruct Property Lines. >Fence Ownership is NOT determined.
- >Roof Overhangs, Underground Utilities and/or Footers have NOT been located UNLESS otherwise noted.
  >Septic Tanks and/or Drainfield locations are approximate and MUST

be verified by appropriate Utility Location Companies.

>Use of This Sketch for Purposes other than Intended, Without Written Verification, Will be at the User's Sole Risk and Without Liability to the Surveyor. Nothing Hereon shall be Construed to Give ANY Rights or Benefits to Anyone Other than those Certified.

-Legend-- Point of Curvature PC - Point of Curvature
Pg. - Page
Pl - Point of Intersection
P.O.B.- Point of Beginning
P.O.L. - Point on Line
PP - Power Pole Centerline - Concrete Block - Concrete Monument - Concrete Conc. D DE Description Drainage Easement PRM - Permanent Reference Fasement - Federal Emergency
Management Agency
- Finished Floor Elevation - Point of Tangency R Rad. R&C Radius - Radial - Rebar & Cap Fnd. IP R&C - Rebar & Cap
Rec. - Recovered
Rfd. - Roofed
Set - Set ½" Rebar &
Rebar Cap "LB 7623"
Typ. - Typical
UE - Utility Easement
WM - Water Meter - Iron Pipe - Iron Pipe - Length (Arc) - Measured - Nail & Disk - Non-Radial - Official Records Book N&D N.R. ORB P - Delta (Central Angle) P.B. Plat Book - Wood Fence - Chain Link Fence

Thereby Certify that this Sketch and Description of the above Described Property is True and Correct to the Best of my Knowledge and Belief as recently Surveyed under my Direction on the Date Shown, Based on Information furnished to Me as Noted and Conforms to the Standards of Practice for Land Surveying in the State of Florida in accordance with Chapter 5.17,052 Florida Administrative Codes, Pursuant to Section 472.027 Florida Statutes.

6637 Date Signed: 02/28/23 This Sketch is intended ONLY for the use of Said Certified Parties.

This Sketch NOT VALID UNLESS Signed and Embossed with Surveyor's Seal. File No. IS-115229

## **Sketch of Description**

Existing 15' Utility & Drainage Easement Conservation Area Tract "C8" N 62°25'50" E 104.69'(P) Southerly Line of 15 Utility

Southerly Line of 15 Utility

Representation of 15 Utility Point of Commencement (NW Corner of Lot 32) 5 62° 25'50" W 32.54' Portion to Vacate Existing Screen Enclosed Pool Deck Point of **Beginning** Lot 32 S 20°54'44" E 15.10' N 62°25'50" E 18.39' Lot 31 <u>L3</u> N 14°20'52" W 5.11' <u>L4</u> N 60°14'54" E 9.09' <u>L5</u> N 75°51'43" E 22.92'

Ireland & Associates Surveying, Inc.

800 Currency Circle Suite 1020 Lake Mary, Florida 32746 www.irelandsurveying.com Fax-407.320.8165 Office-407.678.3366

This is NOT a Survey. This is **ONLY** a Description. This Sketch and Description consist of two sheets and

is not full and or complete without both sheets.

NOT to Scale File No. IS-115229