

THROUGH

\*\*\*\*\*STOP WORK\*\*\*\*\*

NOTICE

SEMINOLE COUNTY ENVIRONMENTAL SERVICES DEPARTMENT

NOTICE

Project: Country Club Heights Utilities Rehab

Contractor: Benchmark Construction

In order to avoid a citation for this violation it is necessary to contact the Seminole County Environmental Services Department.

LOCATION: Clyde Ave

DATE: 3/6/23

COMMENTS: Unacceptable construction methods

Laterals Not connected  
causing Sewer spills

No Pipe bursting

Dave McBroorn  
Utilities Inspector

DO NOT REMOVE THIS NOTICE

Detach and bring this portion of the card with you to the Seminole County Environmental Services Department.

LOCATION: Utilities Engineering @ Reflections

DATE: 3/6/23

COMMENTS: \_\_\_\_\_

Permit Number: \_\_\_\_\_

\_\_\_\_\_  
Utilities Inspector, Seminole County